







# Fresa per forare e contornare Z=1



$\phi D$	$L_u$	$L_t$	$\phi S \times A$	Z	Codice
8	20	70	12x40	1	FRPA0303
10	25	75	12x40	1	FRPA0304
12	30	80	12x40	1	FRPA0305
14	30	80	12x40	1	FRPA0306
16	50	100	12x40	1	FRPA0307

# Fresa per forare e contornare Z=1



ØD	Lu	ØSxA	Z	Codice
18	50	20x50	1	FRPA0308
20	50	20x50	1	FRPA0309